

# CESSNA 100 / 200 SERIES


## REPLACEMENT SEAT BELT INSTALLATIONS 3-POINT DIAGONAL RESTRAINT ASSEMBLIES - FIXED STRAP

**This upgrade is applicable to those CESSNA 100/200 series aircraft that are equipped with factory supplied 3-point diagonal front shoulder harnesses.**

These replacement restraint assemblies are constructed to meet the 3000-pound requirements of TSO-C114 and are superior to the older TSO-C22 belt assemblies. They are fabricated using upgraded hardware components and the polyester webbing will provide a longer service life than the previously used nylon material.

Installation of replacement seat belt assemblies is considered to be **PREVENTATIVE MAINTENANCE** per CFR14, Part 43, app A, c, item 14. An appropriately rated pilot or mechanic must make an airframe logbook entry. The aircraft weight and balance remains unchanged.

### HARDWARE CONFIGURATION - FIXED STRAP INSTALLATION



**INSTALLATION:**

1. Remove the existing lap belt / shoulder belt assembly and install the new TSO-C114 belts per the Cessna 100/200 Series Maintenance Manual.
2. Bolt torque value = 60 inch pounds.

**ALPHA AVIATION INC**

*1500 E Main St. ~ Owatonna, MN 55060*

Phone: 1-800-653-5112 Fax: 1-952-856-5158

Email: [cs@alphaaviation.com](mailto:cs@alphaaviation.com) Web: [www.alphaaviation.com](http://www.alphaaviation.com)